Machine Studies
Draft Schedule for Run03-2, 2016

October 10th 0800 – October 11th 0800

Time	Descriptions	Studiers	SR Status
	Monday, October 10, 2016		
0800-0810	Collect XBPM orbit data	OPS	Stored Beam & Injection
0810-???	Recovery of injectors to lower energy		
1000-1100	Monitor L2:AS2 VSWR levels	RF Group	No Injection
0810-2400	Investigate problem with L5	RF Group/ MOM group	No impact
1000-1100	Reboot IOC1ID	Smith, Marty	No impact
1000-1100	Troubleshoot S12A:P4	Bui	No Beam
1000-1100	Investigate S36/C4 vacuum issue	RF Group	No Beam
1000-1100	Take S:IK thyratron measurments	Vanis	No Beam
1000-1100	investigate the loss of communications to the PTB and LTP Bucking supplies after a power outage. siocileave will be rebooted	Hillman/Fors	No Injection
1000-1100	Troubleshoot S11B:V4 readback issue	Vargas	No Beam
1100-1400	Kicker logging testing	Shang/OPS	Stored beam & injection
1000-1400	Bring Rf1 & 3 E-stops into compliance	RF Group	Stored Beam & Injection

1600-2000	Investigate orbit or recover to 324 singlets	Xiao, Sereno	Stored beam & injection
	Wednesday, October 11, 2016		
0000-0700	OPEN		
0700-0800	Prepare for User beam	OPS	Stored Beam & Injection