

Machine Studies

Schedule for Run3-8,2001

September 18, 0800 to 1600

Time	Descriptions	Studiers	SRStatus
	Tuesday, 09/18/01		
0800-0900	Switch from RF3 to RF2 to inspect matching xformer problem, switch to RF1/RF4 for parallel operation	Trento Horan	No beam
0800-0900	change griswolds in some sectors	Putnam	No beam
0800-0830	replace sextupole if still needed	PS group	No beam
0900-1100	Switch to RF1/RF4 for parallel operation, and then switch back, machine must be back to normal by 1100	Horan Nassiri	Store beam and injection
1100-1530	Hybrid fill configuration and bpm setup	Singh Emery	Store beam and injection
1530-1600	Ready for user beam	Yao OPS	Stored beam and injection
	End of Studies		