

Machine Studies

Schedule for Run2-4,2003

June 17, 0800 - 1600

| Time | Descriptions | Studios | SRStatus |
|--------------------------|---|--|----------------------------------|
| Tuesday, 06/17/03 | | | |
| 0800-1000 | Perform FEEPS-EPICS validation at 31ID | Behrndt | no beam |
| 0800-1000 | Access Zone-A to fix 5ID Gap limit switches | Grimmer | no beam |
| 0800-0900 | Reboot and test RF ioc's | DiMonte | no beam |
| 0800-1000 | Waveguide switch from RF2 to RF3, and measure heater curve | Horan RF group | no beam |
| 0800-0900 | Investigate LOVE controller low flow readings in S8 and 11 | Putnam | no beam |
| 0800-0900 | Refresh SF6 in Zone B of the linac | Pasky | no beam |
| 1000-1030 | Restore stored beam | OPS | Stored beam and injection |
| 1030-1230 | BPM study | Singh Erwin Shang Hahne | Stored beam and injection |
| 1230-1500 | Single bunch study | Harkay Yang | Stored beam and injection |
| 1500-1600 | Singlet fill pattern, low emittance, top-up user beam | OPS Yao | Stored beam and injection |